
CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>1</u> of <u>3</u>	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/30/08
Test to be Performed:	Ground Condition:	Supervisor: RT
Smoke: _X Dyed Water:	Dry: X Damp: Wet:	
Manhole ID: S35GG 018	Test ID: 0994-684	Notifications Made: x (Residents, Fire, 311)

**Field Sketch:** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM					Page 2 of 3				
Sewershed: Jones Falls			Compan	Company: Savin Engineers				Date: 7/30/08	
Test to	be Performed:			Ground	Condition			Supervisor: R	Т
Smoke: X Dyed Water:		Dry: _X Damp: Wet:				Supervisor: TYT			
Manhole ID: S35GG 018		Test ID:	0994-684		Notifications Made:X (Residents, Fire, 311)				
<b>Field Sketch:</b> (Show all Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)									
Defect				Source			Drainage	ĺ	Photo
No.		Address		Type	Location	Sector	Area	Severity	Number
	MH 35GG 008			10	02	01	10	03	OB01-01
					<u> </u>		. •		020.0.
				OBSERV	ATION	CODES			
	Source Type	Location	Sector	Severity		Source Type	Location		
01	Main Sewer	Paved Concrete	Public	No Smoke	10	MH Frame Seal	Non-Paved		
	Service Line	Paved Asphalt	Private	Trace		Storm Drain	Field/Woods		
	Cleanout	Paved Other		Moderate		Catch Basin/Inlet			
	Downspout	Driveway	<del> </del>	Major		Storm Manhole	Golf Course		
	Area Drain	Sidewalk	<del> </del>			Storm Ditch	Other		
	Driveway Drain	Curb	<del> </del>	<u> </u>		Excavation	34101		
	Stairwell Drain	Yard- Front	<del> </del>	<del> </del>		Other			
	Foundation Drain	Yard-Back	<del> </del>	<u> </u>	10				
	Building Interior	Yard- Side							

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>3</u> of <u>3</u>	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/30/08
Test to be Performed:	Ground Condition:	Supervisor: RT
Smoke: _X Dyed Water:	Dry: _X Damp: Wet:	
Manhole ID: S35GG 018	Test ID: 0994-684	Notifications Made: x (Residents, Fire, 311)

**Field Sketch:** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



0994-684\_OB01-01